

autoDNA**autoDNA Vehicle History Report**

The report contains available information as of: 2024-09-01 20:58:06 UTC +0200

Language version: PL

575315c1-855fbe22-91a5f3aa-24755853-96e4cab1

**Mazda Series 3****JMZBP6HH601136668****Vehicle age****By production date/model year****5**

YEARS)

8

MONTH

Production date / Model year**2019****According to the first vehicle registration****4**

YEARS)

6

MONTH

Date of first registration**2020-02-14****7 1 2 3 7km****Attention:**This is not the current mileage of the vehicle being checked. The autoDNA system calculates the average mileage of the vehicle based on data from vehicles with similar characteristics: make, model, fuel type, age, etc.**NOTIFICATION CENTER****Stolen Vehicle Databases**

Databases searched 12/12

Service campaigns

Not reported

Vehicle Information

Number of entries 12

Usage Log

Number of entries 13

Price history

Number of entries 1

Odometer readings

Number of entries 14

Damage history

!

Number of entries 3

Register of pledges

country Poland

✓

Not reported

Equipment

i

Number of entries 0

Archival photos

i

Number of entries 1

VIN correctness

i

Unavailable

VEHICLE INFORMATION

Producer MAZDA	Model SERIES 3	Body type HATCHBACK
Fuel type GAS	Engine capacity [cm3] 1998	Producer Country JAPAN
Production date 2019	Engine power 132KW (179HP)	Number of seats 5
Net weight [kg] 1320	Maximum gross vehicle weight [kg] 1929	Maximum vehicle combination weight [kg] 3229

SERVICE CAMPAIGN

✓

Not reported

STOLEN VEHICLE DATABASE

Databases searched12

It was noted0

Italy

Stolen Vehicle Register - Police

✓

Not reported

The czech republic

Stolen Vehicle Register - Police

✓

Not reported

Romania

Stolen Vehicle Register - Police

✓









Not reported

Lithuania


Stolen Vehicle Register - Police

✓

Not reported

<div><div> Slovenia</div><div>Stolen Vehicle Register - Police</div><div><div>✓</div>Not reported</div></div>	<div><div> Netherlands</div><div>Stolen Vehicle Records - Crimimail Repositories and the Association of Insurers</div><div><div>✓</div>Not reported</div></div>
<div><div> Canada</div><div>Stolen Vehicle Register - Police</div><div><div>✓</div>Not reported</div></div>	<div><div> Slovakia</div><div>Stolen Vehicle Register - Police</div><div><div>✓</div>Not reported</div></div>
<div><div> Sweden</div><div>Register of stolen vehicles - Association of Insurers</div><div><div>✓</div>Not reported</div></div>	<div><div> Norway</div><div>Stolen Vehicle Records - Ettersokt</div><div><div>✓</div>Not reported</div></div>
<div><div> Kaynin</div><div>Stolen Items Register - Kaynine (Germany)</div><div><div>✓</div>Not reported</div></div>	<div><div> Internet database</div><div>Stolen Vehicle Records - Independent Internet Sources</div><div><div>✓</div>Not reported</div></div>

VEHICLE HISTORY



28/04/2024

Policy valid until **2024-06-26**Country **Poland****Vehicle insurance**Policy valid until **2024-05-27**Country **Poland**

10/04/2024

Price/value noted**PLN 103,000 gross**

10/04/2024

Odometer reading reportedOdometer reading
88,000 km

03.2024

Service or vehicle inspectionOdometer reading
87,171 kmCountry **Poland**

08.03.2024

Vehicle insurancePolicy valid until **2025-03-07**Country **Poland**

01.2024

Damage was reported to the vehicleSum **4,500 - 5,000 PLN****Result****BODYWORK DAMAGE****Parts group**

- External body elements

Country **Poland****Damage zone**

- Back
- Left rear
- Right rear

2023

10.2023

Service or vehicle inspectionOdometer reading
77,765 km**Regular service**

Brake Fluid Replacement Engine
Air Filter Replacement

09.2023

Oil and oil filter change Carbon cabin
filter replacement Bodywork inspection

CountryPoland

Service or vehicle inspection

Odometer reading
76,729 km

CountryPoland

08.2023

Damage was reported to the vehicleSum**7,000 - 8,000 PLN**


Result



BODYWORK DAMAGE

Parts group

- External body elements



Damage zone

- Left front
- Left side

CountryPoland

14.02.2023

Vehicle insurancePolicy valid until**2024-02-13**

CountryPoland

08.02.2023

Re-registration of a vehicle due to a change of ownership

Registered to a natural person Place of
registration**Wroclaw, Lower Silesia**

CountryPoland

25/01/2023

An additional technical inspection was performed

Odometer reading
61,395 km

Vehicle inspection after being involved in an accidentResult**Positive**

CountryPoland

25/01/2023

A periodic technical inspection was performed

Odometer reading
61,395 km

Result**Positive**Technical inspection date**2025-01-25**

CountryPoland

01.2023

Service or vehicle inspection

CountryPoland

Odometer reading
61,373 km

2022

10.2022

Odometer reading reported

Odometer reading
61,373 km

10.2022

Damage was reported to the vehicle

Sum**30,000 - 34,000 PLN**

Result



MECHANICAL DAMAGE



INTERIOR DAMAGE




BODYWORK DAMAGE

Parts group

- Passive safety system
- External body elements
- Body construction elements
- Upholstery

CountryPoland



Damage zone

- Left front
- Left side
- Right side
- Left rear
- Central part

08.2022

Service or vehicle inspection

Odometer reading
58,415 km

Regular service

Oil and oil filter change Carbon cabin
filter replacement Bodywork inspection

CountryPoland

14.02.2022

Vehicle insurance

Policy valid until**2023-02-13**

CountryPoland

2021

10.2021

Service or vehicle inspection

Odometer reading
39,330 km

Regular service

Brake fluid replacement

03.2021

Engine air filter replacement Oil and oil filter change Carbon cabin filter replacement Bodywork inspection

CountryPoland

Service or vehicle inspection

Odometer reading
24,614 km

CountryPoland

14.02.2021

Vehicle insurance

Policy valid until2022-02-13

CountryPoland

2020

12.2020

Service or vehicle inspection

Odometer reading
20,136 km

Regular service

Oil and oil filter change Carbon cabin filter replacement Bodywork inspection

CountryPoland

18/02/2020

Start of warranty period

14.02.2020

Vehicle insurance

Policy valid until2021-02-13

CountryPoland

14.02.2020

Vehicle registered

Factory homologated

CountryPoland

14.02.2020

First vehicle registration

02.2020

Service or vehicle inspection

Odometer reading
5km

Preparing the vehicle for delivery

CountryPoland

INSPECTION LOG

Date and time	Type of service	IP	Location
2024-08-27 08:08:04	autoDNA report	91.197.XXX.XXX	Syców, Poland

EQUIPMENT

Description --

ARCHIVE PHOTOS OF THE VEHICLE

10/04/2024

Number of photos 1



Terms and Conditions

All information provided via the autoDNA website is of an auxiliary nature and constitutes only guidelines for the User.

The information contained in the autoDNA service may be subject to change without prior notice from AUTODNA Sp. z o.o. of this fact. All content and graphic signs posted on the autoDNA service are protected by copyright belonging to AUTODNA Sp. z o.o. The use of this content or graphic signs in a manner other than expressly permitted by the terms of the autoDNA service Regulations constitutes its infringement and a breach of applicable provisions of law, in particular the provisions of the Act of 4 February 1994 on copyright and related rights (consolidated text: Journal of Laws of 2006, No. 90, item 631).

The User may download single copies of materials published on the autoDNA service only for personal use. It is prohibited to reproduce, copy, send, store in systems, translate into another language or in any other way, contrary to the Regulations of the autoDNA service, use the content made available via the autoDNA service, without the prior, express, written consent of AUTODNA Sp. z o. o.

AUTODNA Sp. z o. o. may have patents, patent applications, copyrights, trademarks and other intellectual property rights relating to the content made available through the autoDNA service in any form.

AUTODNA Sp. z o. o., by providing content via the autoDNA service, does not grant a license for patents, copyrights, trademarks or other intellectual property rights contained in the provided content.

The names of entities or products contained in the content made available by AUTODNA Sp. z o. o. in any form through the autoDNA service may constitute registered trademarks or service marks of such entities.

autoDNA**Vehicle History Report
autoDNA**

JMZBP6HH601136668

Mazda Series 3

**How to scan QR code**

Launch your phone's camera and point the phone's lens at the QR code. The phone will automatically scan the QR code. Alternatively, launch a QR scanning app and proceed similarly.

**How to stick on glass**

Stick it on the side window of your car, on the right or left side. We do not recommend sticking it on the windshield, which is set at an angle, making it harder to scan the QR code.

**How to put a picture in an ad**

Add a QR code as another photo to your ad. Popular services allow you to add a photo up to 5 MB in size and 1080 x 720 px resolution. The file you received from us with the ordered report meets these requirements. Simply add a photo to the gallery of the vehicle being sold.